


**ELECTRICAL CONNECTION**

Parallel two electromagnet to 12 volt DC power source. Make sure the center of one electromagnet is north and the other is south. The two electromagnets are arranged to attract each other.



**PERMENTANT ASSEMBLY**

Once the desired spacer(s) are fixed and will not alter in the future. The spacer(s) can be welded on the electromagnets permanently.

**CAUTION: ALWAYS WEAR GLOVES TO AVOID PINCH, BECAUSE THE ELECTROMAGNETS ARE ATTRACTIVE TO EACH OTHER!**

MAGNETECH CORPORATION NOVI, MICHIGAN USA (248) 426-8840	SIZE A	DWG BY VWL	DWG NO. MFG Flux Generator Assembly		REV
	SCALE	DATE	3-30-04	SHEET	